



Ground Fault Protection Improvements to Prevent Fires

Description of problem
and potential solutions

Presented by

Bill Brooks, PE

Principal, Brooks Engineering

Code Official Panel Lead, SolarABCs



Ground-Fault Protection Blindspot

Recent fires on large PV Systems have had similar origins

- April 5, 2008 – Bakersfield, California
- April 16, 2011 – Mount Holly, North Carolina
- May be others (several)



Common Elements in Fires

- Undetected fault in a grounded conductor that can continue indefinitely. Undetected fault becomes new “normal” and the ground fault fuse does not blow.
- Ungrounded conductor fault occurs some time after grounded conductor fault. This fault blows the ground fault fuse but instead of interrupting the fault, short circuit current persists in the array.


Solar America Board for Codes and Standards

Collaborate • Contribute • Transform



Typical Sequence of Events

Stage 1- Faulted Grounded String Conductor




Solar America Board for Codes and Standards

Collaborate • Contribute • Transform



Typical Sequence of Events




Solar America Board for Codes and Standards

Collaborate • Contribute • Transform




Typical Sequence of Events






Typical Sequence of Events

Stage 1- Faulted Grounded Subarray Conductor





Typical Sequence of Events



Solar America Board for Codes and Standards


Collaborate • Contribute • Transform



Typical Sequence of Events

Stage 1- Faulted Grounded String Conductor

Stage 2- Faulted Ungrounded Subarray Conductor



Solar America Board for Codes and Standards

Collaborate • Contribute • Transform



Typical Sequence of Events

Conductor

CB1 22 STRING
SUBARRAY

136 AMPS

CB2 22 STRING
SUBARRAY

136 AMPS

CB3 22 STRING
SUBARRAY

136 AMPS

952 AMPS

**FAULTED CONDUCTOR
INSULATION DAMAGE IN
SUBARRAY CONDUCTOR**

136 AMPS

1088-AMPS

136 AMPS

300A FUSE

300A FUSE

300A FUSE

300A FUSE



**ARRAY COMBINER FUSE
300A, 600VDC FUSE DESIGNED
TO HOLD (NOT CLEAR) FOR 60
SECONDS AT 952-AMPS.**

Combiner Box 8

F1


F2

F15





Typical Sequence of Events



BURNING CONDUCTOR
INSULATION ON 10AWG CONDUCTOR IGNITES AT HIGH CURRENT IGNITING MODULES AND OTHER NEARBY FUEL


Solar America Board for Codes and Standards

Collaborate • Contribute • Transform



Typical Sequence of Events

Stage 1- Faulted Grounded Subarray Conductor
Stage 2- Faulted Ungrounded Subarray Conductor



Solar America Board for Codes and Standards

Collaborate • Contribute • Transform



300A FUSE

1088-AMPS

136 AMPS

136 AMPS

136 AMPS

•

•

•

952-AMPS

136 AMPS

5A
FUSE

0-AMPS

ARRAY COMBINER FUSE
300A, 600VDC FUSE DESIGNED
TO HOLD (NOT CLEAR) FOR 60
SECONDS AT 952-AMPS.

HIGH FAULT
CURRENT CLEARS
GFP FUSE
ALLOWING ARRAY
SHORT CIRCUIT
CURRENT TO
FLOW THROUGH
THE TWO FAULTS

ARCING CONDUCTOR

HIGH CURRENT CAUSES CONNECTION TO MOVE SLIGHTLY FROM GROUNDING POINT INITIATING AN ARC THAT CONTINUES UNTIL ARRAY COMBINER FUSE CLEARS IN 60 SECONDS



“Blindspot”

- Established GFDI limits are larger for larger PV systems
- Current examination of the evidence suggests faults on the grounded array conductor can exist without tripping the ground fault fuse
- Higher ground-fault trip threshold also yields a larger blind-spot



Solar ABCs Project

- White Paper
- Research
- Report with Recommendations



White Paper

- Describe Problem
- Describe planned research to identify possible causes
- Discuss tests to determine if specific installations can detect faults on the grounded conductor
- Identify possible solutions



Research

- Characterize the conditions where the existing ground-fault protection may be inadequate
- Develop mitigation proposals
 - Implement through changes to NEC and UL Standards
 - Working proposal is a combination of a morning check and measurement of differential current.



What about Existing PV Systems with Blindspot?

- Current evidence suggests the need for the following:
 1. proper installation techniques with close attention to wire management,
 2. annual preventative maintenance actions to identify and resolve progressive system damage,
 3. detailed data acquisition to monitor the operation of all PV systems at a level sufficient to determine if unscheduled maintenance is required, and,



What about Existing PV Systems with Blindspot?

4. Possible need to add additional ground fault and PV array isolation sensing devices
- Possible options to be confirmed through research:
 - Retrofit large systems with more sensitive Residual Current Monitors (300mA or less)
 - Where possible, apply daily array insulation test before starting the inverter.



Possible Design Recommendations for Future PV Systems

- Possible options based on future research:
 - Employ retrofit recommendations up front for grounded PV arrays.
 - UNGROUND the array
 - Employ segmenting contactors to reduce current during faults.
 - Arc Fault Detectors (2011 NEC)
 - Module level control to react to faults



Ongoing Codes and Standards Efforts

- UL 1741 that governs PV inverters is being revised to address the blind spot in inverters
- The 2014 National Electrical Code has several proposals that address code concerns related to the blind spot.
- CMP4 Task Group on firefighter safety submitted a proposal to the 2014 NEC that would require all PV systems on buildings to have module-level control.